OFFICE OF THE CHIEF FIRE OFFICER KARNATAKA FIRE AND EMERGENCY SERVICES KALABURAGI ZONE KALABURAGI-585103.

## Office of the chief Fire Officer

Karnataka State Fire & Emergency Servicers, Kalburagi-03



## No:273:CFO/NOC/ADVICE/2024

DATE:27/12/2024

To,

THE PRINCIPAL/MANAGER
SATYAM INTERNATIONAL SCHOOL
LOCATED AT KAPPAGAL ROAD
BALLARI TOWN BAL LAR1-583101.

Sir,

**Sub:-** Issue of "Fire Safety Recommendations" on requirement of fire Prevention fire fighting and evacuation measures required at SATYAM INTERNATIONAL SCHOOL LOCATED AT KAPPAGAL ROAD BALLARI TOWN BALLARI-583101.

Ref:- 1) Applicants letter Dated 07/11/2024

2) C.No.836/RFO/Ballari/2024, Date- 25-12-2024

\*\*\*\*\*\*

With reference to the subject above cited, the premises of SATYAM INTERNATIONAL SCHOOL LOCATED AT KAPPAGAL ROAD BALLARI TOWN BALLARI-583101.was inspected by, Regional Fire Officer, Ballari on 13/11/2024 with respect to fire prevention, fire lighting and evacuation measures to be Provided in the above premises and Submitted building details as under.

## A. Details of the Building/Premises:-

01.	Name and Address of the applicant.	:	THE PRINCIPAL/MANAGER
			SATYAM INTERNATIONAL SCHOOL
			LOCATED AT KAPPAGAL ROAD
-			BALLAR1 TOWN BALLARI-583101
02.	Name and Address of the premises.	:	SATYAM INTERNATIONAL SCHOOL
			LOCATED AT SY NO 16A / 1 KAPPAGAL ROAD
			BALLARI TOWN BALLARI-583101
03.	Name and Address of the Building	:	MANAGEMENT,
	owner.		SATYAM INTERNATIONAL SCHOOL
			LOCATED AT KAPPAGAL ROAD
			BALLARI TOWN B.ALLARI-583101
04.	Number of Buildings	:	01 No's of Building.
05.	Number of floors	:	Ground + 2 Upper floor.
06	Floor-wise details of occupancy:-	:	
	Ground floor:	:	1) Principal chamber -01No
			2) Staff Room-01 No
			3) Correspondence Office-01
			-4) Waiting room-01No

ctyam International School CBSE AFF. No. 830478 Kappagal Road, BALLARI.

FOR SATYAM INTERNATIONAL SCHOOL

Secretary & Correspondent

Solution   Staff Room-16 No's   Records room-01No   Records room	Y		piormirmo			
7) Store Room-01No 8) Art And Craft Room-01No 9) Sports Room-01No 1" floor: : 1) Class Room-09No's 2) Library-01No 3) Lab-05No 4) Language Room-01 5) Staff room-01No 6) Store room-01No 2" floor: : 1) Class Room-14 No's 2) Auditorium-01No 3) Staff Room-01No 4) Store room-01No 07 Height of the building : 11.10 Mtrs 08 Site area : 07.00 Acres 09 Built-up area of each floor :- First Floor—Second			:	,		
8   Art And Craft Room-0lNo   9   Sports Room-0lNo   9   Sports Room-0lNo   1" floor:   1   Class Room-09No's   2   Library-0lNo   3   Lab-05No   4   Language Room-0l No   6   Store room-0lNo   5   Staff room-0l No   6   Store room-0lNo   6   Store room-0lNo   1   Class Room-14 No's   2   Auditorium-0lNo   3   Staff Room-0lNo   4   Store room-0lNo   4   Store room-0lNo   4   Store room-0lNo   6   Store room-0lNo   7   Store room-0lNo				,		
1" floor:   1) Class Room-0lNo				A CONTRACTOR OF THE PROPERTY O		
1" floor:   1   Class Room-09No's   2   Library-0lNo   3   Lab-05No   4   Language Room-01   5   Staff room-01No   6   Store room-0lNo   6   Store room-0lNo   1   Class Room-14 No's   2   Auditorium-0lNo   3   Staff Room-0lNo   4   Store room-0lNo   4   Store room-0lNo   4   Store room-0lNo   1   1.10 Mtrs   1   1   1   1   1   1   1   1   1				The state of the s	-0lNo	
2						
3) Lab-05No     4) Language Room-01     5) Staff room-01No     6) Store room-01No     6) Store room-01No     7		1" floor:	;	,		
4   Language Room-01   5   Staff room-01 No   6   Store room-01No   7   Class Room-14 No's   2   Auditorium-01No   3   Staff Room-01No   4   Store room-01No   6   Store room-01No   7   Store room-01No   Store room-01No   7   Store room-01No   Store room-01No   7   Store room-01No   S						
Staff room-01 No						
2" floor: : 1) Class Room-14 No's 2) Auditorium-0lNo 3) Staff Room-0lNo 4) Store room-0lNo 11.10 Mtrs  8 Site area : 07.00 Acres  9 Built-up area of each floor:  Ground Floor—First Floor—Second Floor—Second Floor—Second Floor—Second Floor—1807.90 Sq.Mtr 1807.90 Sq.Mtr		*				
2" floor:   1) Class Room-14 No's   2) Auditorium-0lNo   3) Staff Room-0lNo   4) Store room-0lNo   4) Store room-0lNo   5				,		
2) Auditorium-0INo 3) Staff Room-0INo 4) Store room-0INo  11.10 Mtrs  11.10 Mtrs  12.11.10 Mtrs  13.11.10 Mtrs  14.11.10 Mtrs  15.11.10 Mtrs  16.11.10 Mtrs  17.11.10 Mtrs  1807.90 Sq.Mtr						
3) Staff Room-0lNo 4) Store room-0lNo 4) Store room-0lNo  Total built-up area  (Front) East  3) Staff Room-0lNo 4) Store room-0lNo 4) Store room-0lNo 4) Store room-0lNo 11.10 Mtrs 11.10 M		2" floor:	:			
4) Store room-0lNo  07 Height of the building : 11.10 Mtrs  08 Site area : 07.00 Acres  09 Built-up area of each floor :-  First Floor—Second Floor—Second Floor—Second Floor—1807.90 Sq.Mtr  10 Total built-up area : 5421.27 Sq mtr.  11 Surrounding properties:-  (Front) East : Sy.no.16B kappagal village Road				,		
07 Height of the building : 11.10 Mtrs  08 Site area : 07.00 Acres  09 Built-up area of each floor :-  Ground Floor — : 1807.90 Sq.Mtr						
08       Site area       : 07.00 Acres         09       Built-up area of each floor :-       : 1807.90 Sq.Mtr         First Floor - Second Flo				,		
09 Built-up area of each floor:-  Ground Floor—First Floor—Second Floor—Second Floor—Second Floor—Second Floor—Second Floor—First Floor—Second Floor			:			
Ground Floor—First Floor—Second	08	Site area	:	07.00 Acres		
First Floor—Second Floor—1807.90 Sq.Mtr  10 Total built-up area : 5421.27 Sq mtr.  11 Surrounding properties:-  (Front) East : Sy.no.16B kappagal village Road	09					
Second Floor— 1807.90 Sq.Mtr  10 Total built-up area : 5421.27 Sq mtr.  11 Surrounding properties:-  (Front) East : Sy.no.16B kappagal village Road		Ground Floor —	:	1807.90 Sq.Mtr	/	
10 Total built-up area : 5421.27 Sq mtr.  11 Surrounding properties:-  (Front) East : Sy.no.16B kappagal village Road		First Floor —		1807.90 Sq.Mtr		
Surrounding properties:-  (Front) East : Sy.no.16B kappagal village Road		Second Floor —		1807.90 Sq.Mtr		
(Front) East : Sy.no.16B kappagal village Road	10	Total built-up area		5421.27 Sq mtr.		
	11	Surrounding properties:-				
		(Front) East	:	Sy.no.16B kappagal village Road		
(Rear) West  :   Sy No 16A2		(Rear) West	:	Sy No 16A2		
(Side) North : Sy No 15/A		(Side) North	:	Sy No 15/A		
(Side) South : Sy No 22/A		(Side) South	:	Sy No 22/A		
12. Set back area available around the Building:-	12.					
(Front) East  :   06.00Mtrs.   The set backs all around the		(Front) East	:	06.00Mtrs.	The set backs all around the	
(Rear) West : 33.00 mtrs. Building to be maintained as		(Rear) West	:	33.00 mtrs.	_	
(Side) North: 01.50 mtrs. Per zonal regulations.		(Side) North	:	01.50 mtrs.	Per zonal regulations.	
(Side) South: 09.10 mtrs.	***************************************	(C:1-) C4-		00 10 mtrs		

B. On inspection of this Educational premises, the following fire prevention, fire fighting and evacuation measures are recommended & are considered absolutely essential from fire safety point of view:-

sale	y point of view:-		
Sl. No. [ 01 ]	Details [ 02 ]	Existing [ 03 ]	Recommendations [ 04 ]
01	Accessibility to Premises.	The premises is accessible from 09.00 mtrs wide Road Located on the Eastern Side.	Adequate
02	No of entrances.	01 No of entrance provided	Complied
03	Width of entry/ exit	03.50 meters Width	Adequate
04	Diesel generators.	Provided	Adequate

PRINCIPUL Name international School CBSE AFF. No. 830478 Tagal Road, BALLARI.

For SATYAM INTERNATIONAL SCHOOL

R-V-gasteclic Lav

Secretary & Correspondent

		l No Generat	tor (	of 150 KVA Capacity	
05	No. of staircases available	No of staircase	:	02 No's of Staircases Provided	Recommended to provide Additional 02No's of staircases of width 1.50 mtrs.
		Width of	:	01.50Mtr.	
		staircase			4
		Width of	:	30 cm	/
		treads			
		Height of	:	15 cm Mtrs	
		risers			
		No of riser	:	16 risers provided	
		per flight		In a flight per/Flight	
		Height of	:	01.00 Mtrs.	
		handrails			
		Head room	:	02.25 Mtrs.	
		clearance			
06	No of lifts and	No of lifts	:	NIL	
	capacity. No of patients lifts.	Capacity of lifts	:	NIL	
07	Fire extinguisher		Pro	vided	
		<ol> <li>03 No's ABC fire extinguishers each of 5.0 Kg Capacity,</li> <li>05 No's of DCP Fire Extinguishers of 5 Kg Capacity,</li> <li>02 No's of CO2 Fire Extinguishers of 4.50 Kg Capacity,</li> </ol>			
08	Public address system	Provided			
09	Safe Assembly Area	Provided			

Salyam International School
CESE AFF. No. 830478
Kappagal Road BALLARI.

The state of the s

For SATYAM INTERNATIONAL SCHOOL

R. Vongasteelh Www. Secretary & Correspondent

10	First Aid Kit	Provided	1	
dis-adjoint and dis-adjoint and dis-	î.			
11	Hose Reel Hose System	Provided		
12	Fire prevention measures	Recommended	1) Explosive and Inflammable mater Is Should not be stored In the premises. 2) Accumulation of Combustible waste in And around the premises Should be avoided 3) The class room and other door shall not be Kept locked Hatched During working hours And shall be free from Obstructions. 4) C.C. cameras so provided all around the school building at the strategic location to be maintained. 5) On site and off site emergency plans must be prepared the mock evacuation drill must be conducted twice a year.	
13	Terrace tank Or Over Head Tank	Provided over head tank 10000 ltrs capacity.	Recommended to provide terrace tank of 10,000 ltrs water capacity hose reel hose system  And 10,000 ltrs water capacity Under ground tank.	
14	At the terrace tank level with minimum pressure of 3.5 kg/cm2	Provided.		
15	Fire Control Room At Ground Floor	Not Provided.	Separate Fire Control Room at Ground Floor near by staircase.	
<u> </u>				

Satyam International School Sc

For SATYAM INTERNATIONAL SCHOOL

R. Jacella Dur

Secretary & Correspondent

16	Escape routes Sinages (EXIT SIGN BOARD)	Provided.	
17	Fire order	Not Provided.	Recommended to provide The action to be taken by the management/teacher & the students in case of any emergency to be displayed with the telephone No of fire station BALLARI i.e 08392-266001 & 101 the telephone no of police station & hospitals.
18	Fire fighting training.	04 No's of Employees have undergone training in Fire Fighting at R.A.Mundkur Karnataka State Fire & Emergency Services Academy, Bannerghatta Road, Bangalore from 19-12-2024 to 21-12-2024  1) Sri Kshitish Poi 2) Sri Gayatri 3) Nagabhooshan Gouda K 4) Sri Neelakanta K	Recommended to train At-least 40% Of School Staff shall be got trained in basic fire fighting at R.A.Mundkur fire & Emergency Services  Academy, Bannerughatta road, Bangalore within 3 months or at an early date is a mandatary

Hence this "Fire Safety Recommendation" is issued to SATYAM INTERNATIONAL SCHOOL LOCATED AT KAPPAGAL ROAD BALLARI TOWN BALLARI-583101 subject to strict adherence of the conditions as laid down in this Recommendations and to check the portable fire extinguishers & the Hose reels and pumps and to conduct mock drills periodically And the management must not extend the height of the building beyond 15.0 meters. and this Recommendations is valid for a period of two year from the date of issue.

Copy to: The Regional Fire Officer, Ballari, Range Ballari.

Case AFF. No. 830478
Kappagal Road, BALLARI.

CHIEF FIRE OFFICER 27 US KARNATAKA FIRE AND EMERGENCY SERVICES KALABURAGI ZONE KALABURAGI-585103. For SATYAM INTERNATIONAL SCHOOL

Yours Faithfully

1. Vogadeelh on

Secretary & Correspondent